



# DEPARTMENT OF FORESTRY AND FIRE PROTECTION

OFFICE OF THE STATE FIRE MARSHAL  
Fire and Life Safety Division - South  
602 E Huntington Dr, Suite A, Monrovia, CA 91016  
(626) 305-1908

## SPOT INSPECTION REPORT

### LOCATION INFORMATION

**Building Name:** BA SELF STORAGE - H BLDG

**Street Address:** 620 N Heliotrope Dr.

**County:** Los Angeles

**City, State, Zip code:** Los Angeles, CA, 90004

**Lot Number:**

**Suite Number:**

**Floor Number:**

**Agency:** Transportation Dept. (CalTrans) (59900)

**SFM File No.:** 14-19-81-1437-10008

### INSPECTION INFORMATION

**Inspection Number :** 152999

**Inspection Type:** Spot Inspection

**Inspection Date :** 12/07/2023

**Inspection Status :** Failed

**Inspector:** Ryan Hernandez

**Inspection Hours :** 2

**Inspector Signature:**

**Travel Hours :** 1

**Inspection Comments:** On 12/07/23 a fire and life safety inspection was conducted by DSFM Hernandez and DSFM Beihl and accompanied by Caltrans Airspace Right of Way Agent Shannon Burton.

The following deficiencies were noted and require corrective action. Please call or email to schedule a re-inspection.

For any questions, please call the Monrovia Field Office at (626) 305-1908.

**Discussed With:** Rachel Kim

**Title:** Senior Right of Way Agent

**Accompanied By:**

**Title:** Senior Right of Way Agent

\_\_\_\_\_  
Rachel Kim

**Signed:**

**COMMENTS OR QUESTIONS ABOUT INSPECTION SERVICES**  
Please contact Life Safety South at (626) 305-1908 for assistance.



# DEPARTMENT OF FORESTRY AND FIRE PROTECTION

OFFICE OF THE STATE FIRE MARSHAL  
Fire and Life Safety Division - South  
602 E Huntington Dr, Suite A, Monrovia, CA 91016  
(626) 305-1908

## SPOT INSPECTION REPORT

### Violation # 701305

**Description:** 511068

**Violation Code:** Title 24 CFC 2022-315.3.1

**Comments:** Storage shall be maintained 2 feet (610 mm) or more below the ceiling in non-sprinklered areas of buildings or not less than 18 inches (457 mm) below sprinkler head deflectors in sprinklered areas of buildings.

The following locations require storage to be lowered from the ceiling. A mandatory compliance inspection is required within 30 days of this report.

Unit #H22



**Comments:** Unit #H22